

## PHOTOGRAPHS

PRE CONTRACT WORKS



COMPLETED WORKS



Temporary fencing replaced with permanent painted palisade type fencing. (Fence has been painted since this photograph was taken).



Builders rubbish and construction materials cleared from adjacent undeveloped area.



Overgrowth rubble & rubbish cleared from site (port cabins also removed since this picture was taken).

## PHOTOGRAPHS

PRE CONTRACT WORKS



COMPLETED WORKS



Overgrowth rubble & rubbish cleared from site (port cabins also removed since this picture was taken).



Overgrowth rubble & rubbish cleared from site (port cabins also removed since this picture was taken).