

PHOTOGRAPHS

Please see below progress photographs from our site visit carried out 1st October 2013 for works completed to Stocking Wood Housing Estate.

COMPLETED WORKS



Boundary fencing to undeveloped section of lands in place to prevent unauthorized access.



Boundary fencing to undeveloped section of lands in place to prevent unauthorized access.

PHOTOGRAPHS

Please see below progress photographs from our site visit carried out 1st October 2013 for works completed to Stocking Wood Housing Estate.

COMPLETED WORKS



Boundary fencing at entrance to undeveloped section of lands in place to prevent unauthorized access.



Boundary fencing to undeveloped section of lands in place to prevent unauthorized access.

PHOTOGRAPHS

Please see below progress photographs from our site visit carried out 1st October 2013 for works completed to Stocking Wood Housing Estate.

COMPLETED WORKS



Gates erected to prevent unauthorized access to undeveloped lands.



Boundary fencing to undeveloped section of lands in place to prevent unauthorized access.