

Photos



A view of the front of 2 Lealand Walk on 13 / 03 / 2013. Number 2 is to the right of the public lighting column



A view of the back of 2 Lealand Walk on 13 / 03 / 2013. Note the stains and dampness on the wall, the cable and the breach in the plywood sheet which secures one window opening at first floor level.